

Queue Number	2792413	Transaction Date	23 Sep 2026, 16:02:43
Site Name	840 - Emirates Auctions	Transaction Number	34292909 (CC10010) (CC10025)



Vehicle Details

Chassis Number	JM7DKAW77L*****
Specification	GCC Specification
Make	Mazda
Model	CX3
Model Year	2020
Color	Blue
Mileage	171773 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED REFITTED , REAR LEFT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED , FRONT LEFT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED .	الارضية
01.F Bumper	MISALIGN , HOOK COVER MISSING	دعامية
01.G Trunk	REFITTED	صندوق
02 Chassis Condition		
02.A Chassis	CHASSIS COVERED ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		
03.A Engine Visual Condition	OIL LEAK .	الحالة النظرية للمحرك
04 Seats Condition		
04.A Seat Condition	EXTRA COVER PORTION CRACK	حالة المقاعد
05 Transmission Condition		
05.A Gear Box Visual Condition	OIL LEAK .	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2024 , RIGHT SIDE 2023	الاطار الخلفي
06.C Rims Condition	MINOR SENT SCRATCHES	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك و طناير الفرامل
08 Interior Condition		الحالة الداخلية
08.A AC Condition	OK	المكيف
08.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.C Gear Shifting Lever	LOCK COVER MISSING	ذراع نقل السرعات
09 Battery Condition		حالة البطارية
09.A Battery Condition	WEAK.	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae