



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Sep 2022, 17:35:32
Transaction Number	97957240 (CC10006)	Queue Number	593044



Chassis Number	SALWA2FE2HA124761
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Sport
Model Year	2017
Color	Black
Mileage	127702 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Suspension System		ممتص الصدمات
01.A Arms	LOWER ARM BUSHES CRACK,	أزرع
01.B Ball Joint	BALL JOINT BOOT CUT.	مفصل كروي
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03 Chassis Condition		الشاصي
03.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
04 Exhaust System		نظام العادم
04.A Modification	NOISY.	تعديلات
05 Body		جسم المركبة
05.A Paint	BODY PORTION REPAINTED,PORION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
05.B Doors	RIGHT SIDE BOTH PORTION REPAIRED REPAINTED	أبواب
05.C Bumper	FRONT BUMPER FRAME RUSTY.	دعامية
05.D Floor	UNDER FLOOR COVERED.	الارضية

DEFECT	REMARKS	
06 Interior Condition		الحاله الداخليه
06.A AC Condition	OK	المكيف
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Visual Gear Box Condition	OK	حالة الجير النظرى
08 Engine Condition		المحرك
08.A Visual Engine Condition	OK	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.