



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Jul 2022, 13:16:27
Transaction Number	55052763 (CC10006)	Queue Number	312309



Chassis Number	MDHBN7AD2GG700074
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Sunny
Model Year	2016
Color	Silver
Mileage	177075 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Bumper	MISALIGN	دعامية
01.B Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ
01.C Floor	BACK PANEL REPAIRED	الارضية
01.D Paint	BODY MINOR DENT SCRATCHES & PORTION RUSTY	الصبغ
01.E Sign of back accident		وجود مؤشر لحادث في الخلف
02 Interior Condition		الحالة الداخلية
02.A AC Condition	NOT WORKING	المكيف
03 Tires and Rims Condition		الاطارات
03.A Rear Tyre	BOTH SIDE 2018 WORN OUT	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2018 CRACKED & LEFT SIDE PUNCHER	الاطار الامامي
04 Engine Condition		المحرك
04.A Visual Engine Condition	OK	حالة المحرك النظري
05 Chassis Condition		الشاصي
05.A Chassis	OK	الشاسيه
06 Transmission Condition		الجير

DEFECT	REMARKS	
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Visual Gear Box Condition	OK	حالة الجير النظرى
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Brake Light	RIGHT SIDE PORTION CRACKED	نور الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.