CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877720
Transaction Date	19 Oct 2026, 17:42:11
Site Name	840 - Emirates Auctions
Transaction Number	86637044 (CC10006) (CC10006)



Vehicle Details

Chassis Number	JHMCP26768*******
Specification	GCC Specification
Make	Honda
Model	Accord
Model Year	2008
Color	White
Mileage	388264 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, DENTS, SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY ,	صدأ
01.C Floor	UNDER FLOOR THICK RUST PROOFED PORTION DENTS, OILLY, MUDDY, BACK PANEL REPAIRED	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE , FIX BY SCREW , LOGO GETTING FADED	دعامية
01.E Other	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	اخري
01.F Sign of back accident		وجود مؤشر لحادث في الخلف
01.G Vehicle Color	BROWN	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS GETTING RUSTY , OILLY MUDDY, VISIBLE AREA ONLY END REPAIRED	الشاسيه
03 Engine Condition		المحرك
03.A Mount	UPPER MOUNT BUSHES CRACK	كرسي
03.B Engine Visual Condition	PARTS REFITTED GETTING RUSTY , MINOR OIL LEAK , MUDDY OILLY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	INTERIOR REFITTED ,PORTION DAMAGE	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY , SIGN OF OIL LEAK , MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	WATER TANK DAMAGE	اخري
08 Lights		الاضاءة
08.A Head Light	LENS FADED PORTION CRACK	الاضاءة الرئيسية
08.B Tail Light	LENS FADED PORTION CRACK	الضوء الخلفي
08.C Indicator & Hazard light	HAZARD BUTTON FADED	الاشارات
08.D Fog light	LENS GETTING FADED	كشاف الضباب
09 Brake Condition		الفرامل
09.A Brake Pedal	SPONGY , NOT WORKING ,	دواسة الفرامل
09.B Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	BUSHES CUT	ازرع
10.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
11 Steering Condition		المقود
11.A Steering Boot	BOOT CUT	ربلة المقود
11.B Steering Box	MINOR OIL LEAK	جهاز المقود
11.C Tie Rod End	BOOT CRACK	مؤخرة الرودات
12 Interior Condition		الحاله الداخليه
12.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
12.B AC Condition	NOT COOLING	المكيف
12.C Roof Light	LEFT SIDE NOT WORKING	أنارة السقف
12.D Dash Board	PORTION DAMAGE	لوحة القياده
12.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
12.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
12.G Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
12.H Gear Shifting Lever	KNOB WORN OUT & PANEL DISPLAY AREA REPAINTED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae