



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	06 Sep 2021, 17:32:45
Transaction Number	28783743 (CC10006)	Queue Number	312309



Chassis Number	6G1ZK54F06L840926
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Lumina
Model Year	2006
Color	Red
Mileage	0

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Roof	PORTION REPAIRED & REPAINTED	السقف
01.H Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.I Other	FRONT BUMPER FRAME, RADITOR SUPPORT REPAIRED	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED	كرسي
03.B Other	OIL LEAK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير

DEFECT	REMARKS	
05.A Gear Box	OIL LEAK	الجير
05.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
06 Wipers and Arms		المساحات
06.A Other	WORN OUT	اخرى
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2018 DRY CRACKED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	OK	الاضاءة الرئيسية
08.B Other	OK	اخرى
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	ALL WEAK ,LEAKING & GETTING RUSTY	ممتص الصدمات
10.B Arms	FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED & GETTING RUSTY	ازرع
11 Steering Condition		المقود
11.A Steering Box	STEERING HARD	جهاز المقود
11.B Steering Boot	BOOT CUT & LEAKING DRIPPING	ربلة المقود
11.C Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
12 Interior Condition		الاجزاء الداخلية
12.A Other	SLYDING ROOF INNER SHEILD NOT WORKING PROPERLY & REAR TRUNK NOT CLOSE	اخرى
12.B Mirror	OK	المرايا
12.C AC Condition	A/C NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.