CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2966631
Transaction Date	10 Nov 2026, 11:53:28
Site Name	840 - Emirates Auctions
Transaction Number	21455899 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WBAKB4106B*******
Specification	GCC Specification
Make	BMW
Model	750LI
Model Year	2011
Color	White
Mileage	110366 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FRONT CHASSIS COVERED MUDDY OILY, COVER PORTION DAMAGED PARTS MISSING	الارضية
01.E Bumper	MISALIGN,PORTION CRACKED	دعامية
01.F Windshield	FRONT SPOT CRACK	زجاج
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	REFITTED	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.J Vehicle Model	740LI ON STICKER	طراز المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS COVERED MUDDY OILY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخري
03 Engine Condition		**المحرك**
03.A Other	AIR INTAKE PIPE LOOSE	اخري
03.B Engine Visual Condition	OIL LEAK OPEN REFITTED SHAKING GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	TRANSMISSION FUALT /OPEN REFITTED MINOR OIL LEAK, GETTING RUSTY, JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
05.C Rims Condition	DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Tail Light	RIGHT SIDE MINOR CRACK	الضوء الخلفي
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION REFITTED	اخري
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Steering Oil	MINOR OIL LEAK	زيت المقود
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER PORTION CRACKED, INNER PARTS GETTING RUSTY	اخري
10.B Mirror	LEFT SIDE FOLDING NOT WORKING	المرايا
10.C AC Condition	OK,REAR GRILL DAMAGED	المكيف
10.D Dash Board	LEATHER PORTION CUT	لوحة القياده
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Sunroof	NOT WORKING PROPERLY	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر

wecare@carscheck.ae