



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>27 Jan 2022, 14:32:13</b>
Transaction Number	<b>96923083 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>6T1BF9FKXEX502646</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Camry</b>
Model Year	<b>2014</b>
Color	<b>White</b>
Mileage	<b>277122 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Wipers and Arms</b>		<b>المساحات</b>
01.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	OK	المكيف
02.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING PROPERLY	المرايا
02.C Dash Board	LEFT SIDE HAVE HOLE	لوحة القيادة
02.D Other	CENTER CONSOLE SIDE COVER LOOSE & SLIDING COVER NOT WORKING	اخرى
02.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Fenders	FRONT FENDER REFITTED	مدكار
03.B Bonnet	REFITTED	غطاء المحرك
03.C Trunk	REFITTED	صندوق
03.D Bumper	REPAINTED,MISALIGN	دعامية
03.E Other	FRONT RADIATOR SUPPORT ,BULK HEAD ,BUMPER FRAME REPAIRED&BUMPER FRAME	اخرى
03.F Paint	BODY TOTALY REPAINTED,PORTION REPAIRED , MINOR	الصبغ

DEFECT	REMARKS	
	DENTS, SCRATCHES	
03.G Sign of front accident		وجود مؤشر لحادث في المقدمة
03.H Sign of back accident		وجود مؤشر لحادث في الخلف
03.I Floor	BACK PANEL REPAIRED,BUMPER FRAME BEND	الارضية
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Tail Light	REAR LEFT SIDE LENS DAMAGED	الانارة
04.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	OK	الشاسيه
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
06.B Front Tyre	LEFT SIDE 2017 CRACKED , EXPIRED,WORN OUT & RIGHT SIDE 2018	الاطار الامامي
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Smoke	WHITE SMOKE	دخان
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Arms	FRONT LOWER ARM BUSH CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.