CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906053
Transaction Date	30 Oct 2026, 15:57:07
Site Name	840 - Emirates Auctions
Transaction Number	49411079 (CC10026) (CC10026)



Vehicle Details

Chassis Number	WDDFH34X57*******
Specification	GCC Specification
Make	Mercedes
Model	B 200
Model Year	2007
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.E Windshield	FRONT GLASS BADLY CRACK	زجاج
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED, PARTS REFITTED MINOR OIL LEAK . PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED, PARTS REFITTED MINOR OIL LEAK , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE CRACK & WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE DAMAGE	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CRACK	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY	اخري
11.B AC Condition	NOT CHECK	المكيف
11.C Dash Board	PORTION WORN OUT	لوحة القياده
11.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
11.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.F Air Bag	DAMAGE	وسائد هوائية
11.G Steering Wheel and control buttons	PORTION DAMAGE	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae