

Queue Number 2877756

Transaction Date 20 Oct 2026, 10:43:18

Site Name
840 - Emirates AuctionsTransaction Number
56061456 (CC10010) (CC10010)

Vehicle Details

Chassis Number	WAUZZZF39P*****
Specification	Imported
Make	Audi
Model	Q3
Model Year	2023
Color	Black
Mileage	55557 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED,REFITTED.	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED DENTS SCRATCHES .	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED .	أبواب
01.D Rusty	UNDER PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED ,,CHECKED ONLY VISIBLE AREA .	الارضية
01.F Bumper	MISALIGN ,SCRATCHES.	دعامية
01.G Windshield	FRONT CRACKED.	زجاج
01.H Bonnet	REPAINTED REFITTED. .	غطاء المحرك
01.I Sign of front accident	FRONT ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED ,NOT VISIBLE AREA PROEPRLY ,CHECKED ONLY VISIBLE AREA OK	الشاسيه
02.B Other	NEED TO REMOVE FENDER UNDER COVER FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK COMPONENT PARTS RUSTY UNDR PORTION COVERED,	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	OIL LEAK COMPONENT PARTS RUSTY UNDER PORTION COVERED,	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025/2023 CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الخلفي
06 Lights		الاضاءة
06.A Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES DRY CRACKED.	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخرى
08.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae