CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906103
Transaction Date	30 Oct 2026, 15:57:13
Site Name	840 - Emirates Auctions
Transaction Number	87499739 (CC10010) (CC10011)



Vehicle Details

Chassis Number	JTHBN30F81*******
Specification	Imported
Make	Lexus
Model	LS 430
Model Year	2001
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS RUSTY	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED CHECKED ONLY VISIBLE AREA	الارضية
01.E Bumper	MISALIGN SCRATCHES	دعامية
01.F Bonnet	LOCK DAMAGED,NOT CLOSE	غطاء المحرك
01.G Pillars	RIGHT SIDE A/PILLAR OUTER PANEL REPAINTED PORTION REPAIRED	القوائم
01.H Trunk	NOT OPEN	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.BULKHEAD CRACKED LOOSE	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END LOWE SKIRT DENT , COVERED OILY MUDDY ,REAR LEFT CHASSIS EXTENSION END REPAIRED DENT .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED.	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	BUSHES CUT	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT	ربلة المقود
09.B Steering Box	OIL LEAK	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX LOOSE. INTERIOR PARTS GETTING RUSTY.	اخري
10.B AC Condition	NOT CHECKED . .	المكيف
10.C Dash Board	PORTION BULGED	لوحة القياده
10.D Roof Ceiling	PORTION LOOSE ,GRAB HANDLE MISSING.	بطانه السقف
10.E Odometer reading	NOT CHECKED. .	قراءة عداد المسافات
10.F Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae