CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2981797
Transaction Date	13 Nov 2026, 16:28:02
Site Name	840 - Emirates Auctions
Transaction Number	37103406 (CC10026) (CC10026)



Vehicle Details

Chassis Number	MHFB29F38N*******
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2022
Color	Silver
Mileage	81155 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PARTS THICK RUST PROOFED , PORTION DENT	الارضية
01.E Bumper	MISALIGN, PORTION DAMAGE	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED , REFITTED	غطاء المحرك
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS PORTION COVER , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION WORN OUT , EXTRA COVER	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2021 EXPIRED & RIGHT SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE PANEL LOOSE , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
08.B AC Condition	NOT COOLING	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القياده
08.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
08.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae