



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 09 Mar 2023, 16:58:42 |
| Transaction Number | 74827693 (CC10006) | Queue Number | 683035 |



| | |
|------------------|--------------------------|
| Chassis Number | JN8AY2NY3J9353860 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Nissan |
| Model | Patrol |
| Model Year | 2018 |
| Color | White |
| Mileage | 156315 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|--|------------------------|
| 01 Interior Condition | | الحالة الداخليه |
| 01.A AC Condition | OK | المكيف |
| 02 Body | | جسم المركبة |
| 02.A Trunk | REFITTED | صندوق |
| 02.B Paint | PORTION REPAIRED, REPAINTED, MINOR SCRATCHES ON BODY | الصبغ |
| 02.C Vehicle Model | VEHICLE BODY SHAPE CHANGED TO NEW MODEL | طراز المركبة |
| 02.D Doors | PORTION REPAIRED, REPAINTED, REFITTED | أبواب |
| 02.E Bumper | MODIFIED | دعامية |
| 02.F Fenders | PORTION REPAIRED, REPAINTED, REFITTED | مدكار |
| 02.G Rusty | UNDER BODY PARTS SUSPENSION GETTING RUSTY | صدأ |
| 02.H Bonnet | MISALIGN | غطاء المحرك |
| 03 Transmission Condition | | الجير |
| 03.A Visual Gear Box Condition | OK | حالة الجير النظري |
| 03.B Road Test | NOT CHECKED | فحص علي الطريق |
| 04 Tires and Rims Condition | | الاطارات |

| DEFECT | REMARKS | |
|------------------------------|--------------------------|---------------------|
| 04.A Rear Tyre | BOTH SIDE 2021 | الاطار الخلفي |
| 04.B Front Tyre | BOTH SIDE 2021 | الاطار الامامي |
| 05 Chassis Condition | | الشاصي |
| 05.A Chassis | OK | الشاسيه |
| 06 Engine Condition | | المحرك |
| 06.A Visual Engine Condition | MINOR OIL LEAK | حالة المحرك النظري |
| 07 Seats Condition | | المقاعد |
| 07.A Seat Condition | DRIVER SEAT LOOSE | حالة المقاعد |
| 08 Suspension System | | ممتص الصدمات |
| 08.A Arms | LOWER ARM BUSHES CRACKED | ازرع |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.