

Queue Number 2827666

Transaction Date 07 Oct 2026, 13:29:11

Site Name
840 - Emirates AuctionsTransaction Number
79081570 (CC10010) (CC10010)

Vehicle Details

Chassis Number	W1KZF8DB5M*****
Specification	GCC Specification
Make	Mercedes
Model	E 300
Model Year	2021
Color	Grey
Mileage	89453 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY TOTALLY STICKERING , PAINT NOT CHECKED ..	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR CHASSIS COMPLETE COVERED PORTION DENT MUDDY ,CHECKED ONLY VISIBLE AREA .	الارضية
01.D Bumper	MINOR SCRATCHES .	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	NEED TO REMOVE FENDER COVER UNDER COVER FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED , OILWET ,COMPONENT PARTS RUSTY.ABNORMAL NOISY.	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION FADED.	حالة المقاعد
---------------------	----------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	REFITTED ,OIL WET COMPONENT PARTSRUSTY. GET JERKING.	الحالة النظرية للجير
--------------------------------	--	----------------------

05.B Road Test	NOT CHECKED .	فحص علي الطريق
----------------	---------------	----------------

06 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2024.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024.	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY.	دسك و طناوير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS RUSTY ,SIGN OF WATER FLOODED.	اخرى
09.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae