

Queue Number 2844334

Transaction Date 07 Oct 2026, 14:05:18

Site Name
840 - Emirates AuctionsTransaction Number
49779924 (CC10026) (CC10026)

Vehicle Details

Chassis Number	JTDBR23EX2*****
Specification	GCC Specification
Make	Toyota
Model	Corolla
Model Year	2002
Color	Black
Mileage	391630 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REAPINTED REPAIRED , DENTS SCRATCHES , PORTION FADED , GETTING RUSTY	الصبغ
01.C Doors	FRONT LEFT SIDE WHILE OPEN GETTING SOUND	أبواب
01.D Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR MINOR DENT , MUDDY	الارضية
01.F Bumper	MISALIGN . PORTION DAMAGE	دعامية
01.G Roof	LEFT SIDE TRAIL STRIP MISSING	السقف
01.H Bonnet	REFITTED , MISALIGN	غطاء المحرك
01.I Trunk	REFITTED , MISALIGN, NOT CLOSE	صندوق
01.J Sign of front accident	BUMPER FRAME , FENDER FRAME , RADIATOR SUPPORT RUSTY REPAIRED	وجود مؤشر لحادث في المقدمة
01.K Sign of back accident	BACK PANEL , SPARE WHEEL HOUSING , QUATER PANEL WHEEL ARCH REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS END DENT & REAR BOTH SIDE CHASSIS EXTENSION REPAIRED, RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	FRONT BOTH SIDE SEAT HAVE PLAY , FABRIC WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	ALL SYSTEM NOT CHECKED OPEN REFITTED OIL LEAK DRIPPING . PARTS RUSTY	الحالة النظره للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 EXPIRED CRACK , RIGHT SIDE DAMAGE	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES , REAR RIGHT SIDE CENTER HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE DAMAGE	الضوء الخلفي
07.C Fog light	RIGHT SIDE MISSING	كشاف الضباب
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Suspension Subframe	REAR BOTH SIDE BUSHES CRACK	ممتص الصدمات
09.B Shock Absorber	BUSHES CRACK	
10 Steering Condition		المقود
10.A Steering Oil	MINOR LEAK	زيت المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOXS WORN OUT , INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخرى
11.B AC Condition	NOT CHECK , PANEL SWICTH PORTION WORN OUT	المكيف
11.C Power Window Switch And Glass	MAIN CONTROL PANEL LOOSE FIXS BY SCREW , FRONT LEFT SIDE GLASS LOOSE	مفتاح النافذه و الزجاج
11.D Floor Matting	DIRTY	فرش الأرضيه
11.E Dash Board	DAMAGE , EXTRA COVER	لوحة القيادة
11.F Sun Visor	BOTH SIDE DAMAGE	حاجب الشمس
11.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	WORN OUT	ذراع نقل السرعات
11.J Engine Start Button	KEY DAMAGE	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae