CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899777
Transaction Date	23 Oct 2026, 10:13:29
Site Name	840 - Emirates Auctions
Transaction Number	52928169 (CC10010) (CC10010)



Vehicle Details

Chassis Number	1N4AA5AP9C*******
Specification	GCC Specification
Make	Nissan
Model	Maxima
Model Year	2012
Color	Black
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED,ACCEPT ROOF PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Windshield	FRONT CRACKED .	زجاج
01.F Trunk	DENT MISALIGN ,CHROME SKIRT LOOSE.	صندوق
01.G Door Handle &Lock	FRONT LEFT DOOR LOCK COVER MISSING.	مقابض الأبواب والأقفال
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK APNEL ,CRASH BOX QAURTER PANEL REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	REAR CHASSIS EXTENSION END DENT ,FRONT CHASSIS COMPLETE COVERED OILY MUDY ,	الشاسيه
02.B Other	STEAM WASH CHASSIS FOR INSPECTION.	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	EXTRA COVER PORTION LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED .	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
10.C Axle	BOOT CUT	اكسلات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B Mirror	LOOSE FADED.	المرايا
11.C AC Condition	NOT CHECKED.	المكيف
11.D Dash Board	PORTION LOOSE.	لوحة القياده
11.E Roof Ceiling	PORTION LOOSE	بطانه السقف
11.F Sun Visor	LOOSE.	حاجب الشمس
11.G Odometer reading	NOT CHECKED .	قراءة عداد المسافات
11.H Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.I Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.J Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**