

Queue Number 2841554

Transaction Date 07 Oct 2026, 13:18:39

Site Name
840 - Emirates AuctionsTransaction Number
13926157 (CC10009) (CC10012)

Vehicle Details

Chassis Number	JTEJU3FJ7F*****
Specification	GCC Specification
Make	Toyota
Model	Prado
Model Year	2015
Color	White
Mileage	216097 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY MINOR DENT SCRATCHES	الصيغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR PORTION MINOR DENT	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	RIGHT SIDE CHASSIS GET RUSTY BULGE FRONT END SLIGHT BEND, PORTION MINOR DENT	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET REFITTED GETTING RUSTY,DELAY STARTTING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED, GETTING RUSTY, JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2022 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022 CRACK	الاطار الخلفي

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Head Light	LENS FADED ,HIGH BEAM NOT WORKING	الاضاءة الرئيسية
06.B Tail Light	LEFT SIDE CRACKED	الضوء الخلفي
06.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06.D Fog light	NOT WORKING FADED	كشف الضباب
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
08.B AC Condition	LOW COOLING	المكيف
08.C Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING FORM MAIN SWITCH	مفتاح النافذه و الزجاج
08.D Dash Board	COVER PORTION LOOSE	لوحة القيادة
08.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae