





### Test Certificate

|                     |                        |                    |              |
|---------------------|------------------------|--------------------|--------------|
| Site Number         | : 840-EMIRATES AUCTION | Plate Code         | : 0          |
| Transaction Number  | : 19455517             | Plate Category     | : PRIVATE    |
| Transaction Date    | : 16 MAR 2020 16:03:07 | Plate Number       | : 238435 EA  |
| Queue Number        | : 159502               | Import Doc. Ref.   | :            |
| Chassis Number      | : KNAGN4121C5238435    | Manufacturer/Model | : KIA/OPTIMA |
| Engine Number       | :                      | Model Year         | : 2012       |
| Vehicle Class       | : LIGHT VEHICLE        | Vehicle Color      | : WHITE      |
| Service / Indicator | : DSC AUCTION          |                    |              |

### Statement of Vehicle Condition

| Defect   | Result | Remarks  |
|--|--------|--|
| AUTOMATIC TEST:                                |        |  |
| 13 Brake System                                |        | الفرامل  |
| 13.04 - Brake Test                             | Passed | فحص الفرامل  |
| 16 Side Slip Test                              |        | فحص ميزانية الاطارات                               |
| 16.01 - Side Slip Test                         | Passed | فحص ميزانية الاطارات                               |
| 17 Shock Absorbers Test                        |        | فحص مخمد الصدمات                                   |
| 17.01 - Shock Absorber Test                    | Passed | فحص مخمد الصدمات                                   |
| VISUAL TEST:                                   |        |  |
| 01 Lights                                      |        | الانوار  |
| 01.02 - Tail Lights                            |        | الانوار الخلفية                                    |
|  |        | LEFT SIDE CRACK                                    |
| 02 Steering And Suspension System              |        | عجلة القيادة ونظام التوصيلات                       |
| 02.13 - Stub Axle Assemblies, Boots            |        | المحور   |
|  |        | BOTH SIDE OUTER AXLE BOOTS CRACKS                  |
| 04 Tires Rims                                  |        | الاطارات والعجلات                                  |
| 04.01 - Front Left And Right Hands Tires       |        | الاطارات الامامية                                  |
|  |        | FRONT 2018 & REAR 2016                             |
| 05 Body  |        | الهيكل   |
| 05.09 - Front And Rear Windshields             |        | الزجاج الامامي والخلفي                             |
|  |        | FRONT REPLACED                                     |
| 06 General Items                               |        | الاشياء العامة                                     |
| 06.10 - Mirrors Side View                      |        | المرآيا الجانبية                                   |
|  |        | BOTH SIDE NOT FOLDING & RIGHT ADJUSTER MALFUNCTION |
| 06.14 - Transmission Condition                 |        | حالة ناقل الحركة                                   |
|  |        | OK   |
| 06.16 - Engine Condition, Smoke                |        | حالة المحرك - الدخان                               |
|  |        | ENGINE REFFITED                                    |
| 07 Remarks                                     |        | ملاحظات  |
| 07.04 - Others                                 |        | ملاحظات اخرى                                       |
|  |        | 214811 KM--BONNET REPLACED                         |
| 09 Auction                                     |        | الفحص الكامل                                       |
| 09.02 - Need Wheel Alignment                   |        | يحتاج الى ميزانية العجلات                          |
| 09.06 - Chassis Ok                             |        | النشاصي جيد  |
|  |        | OK   |
| 09.14 - Sign Of Front Accident                 |        | أثر حادث في مقدمة المركبة                          |
|  |        | BULKHEAD REPAIRED                                  |
| 09.24 - Digital Display Damaged/Warning Lights |        | عطل في لوحة التحكم الالكتروني                      |
|  |        | AIR BAG LIGHT ON                                   |
| 09.25 - Body Repainted                         |        | أثر صينغ في المركبة                                |

The Test Certificate Shows the test Result at the time of inspection only.



### Test Certificate

|                     |                        |                    |              |
|---------------------|------------------------|--------------------|--------------|
| Site Number         | : 840-EMIRATES AUCTION | Plate Code         | : 0          |
| Transaction Number  | : 19455517             | Plate Category     | : PRIVATE    |
| Transaction Date    | : 16 MAR 2020 16:03:07 | Plate Number       | : 238435 EA  |
| Queue Number        | : 159502               | Import Doc. Ref.   | :            |
| Chassis Number      | : KNAGN4121C5238435    | Manufacturer/Model | : KIA/OPTIMA |
| Engine Number       | :                      | Model Year         | : 2012       |
| Vehicle Class       | : LIGHT VEHICLE        | Vehicle Color      | : WHITE      |
| Service / Indicator | : DSC AUCTION          |                    |              |

Statement of Vehicle Condition