



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	10 Jan 2022, 18:19:05
Transaction Number	50437623 (CC10006)	Queue Number	312309



Chassis Number	JMYLRH77W2Z705104
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Pajero
Model Year	2002
Color	Silver
Mileage	98568 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Chassis Condition		الشاسي
01.A Chassis	CHASSIS GETTING RUSTY	الشاسيه
02 Steering Condition		المقود
02.A Tie Rod End	BUSHES CRACKED	مؤخرة الروداد
02.B Other	STABILIZER LINK BUSHES DRY CRACKED	اخرى
02.C Rack Pinion	OIL LEAK	مسطرة المقود
03 Suspension System		ممتص الصدمات
03.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
04 Engine Condition		المحرك
04.A Smoke	WHITE SMOKE	دخان
04.B Engine Condition	OIL LEAK	حالة المحرك
05 Lights		الاضاءة
05.A Tail Light	FRONT BOTH SIDE PARK LIGHT NOT WORKING	الانارة
05.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
05.C Head Light	LEFT SIDE LOW & HIGH BEAM NOT WORKING	الاضاءة الرئيسية

DEFECT	REMARKS	
05.D Fog light	LEFT SIDE NOT WORKING	كشاف الضباب
06 Body		جسم المركبة
06.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
06.B Doors	PORTION REPAIRED & REPAINTED	أبواب
06.C Bumper	REPAINTED	دعامية
06.D Roof	REPAINTED	السقف
06.E Trunk	REPAINTED & NOT OPEN FOR CHECK	صندوق
06.F Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS ,FLOOR GETTING RUSTY	صدأ
06.G Paint	TOTALY REPAINTED ,PORTION REPAIRED & DENTS, SCRATCHES ON BODY	الصبغ
06.H Bonnet	REPAINTED	غطاء المحرك
07 Interior Condition		الحالة الداخليه
07.A Mirror	OK	المرايا
07.B Dash Board	INNER BOX LEFT SIDE COVER LOOSE & RIGHT SIDE MISSING	لوحة القيادة
07.C AC Condition	NOT COOLING	المكيف
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	OIL LEAK & GARKING	الجير
09 Wipers and Arms		المساحات
09.A Wiper Arm &Blade	NOT WORKING PROPERLY	ازرع المساحات والشفرات
10 Tires and Rims Condition		الاطارات
10.A Rear Tyre	BOTH SIDE 2017 CRACKED	الاطار الخلفي
10.B Front Tyre	BOTH SIDE 2018	الاطار الامامي
11 Brake Condition		الفرامل
11.A Break Pads	BRAKE WEAK	سفايف الرامل
11.B Brake Pedal	SPONGY	دواسة الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.