

Queue Number 2830698

Transaction Date 03 Oct 2026, 13:00:24

Site Name
840 - Emirates AuctionsTransaction Number
72434475 (CC10013) (CC10011)

Vehicle Details

Chassis Number	SAJAA20A6F*****
Specification	GCC Specification
Make	Jaguar
Model	XJL
Model Year	2015
Color	Unknown
Mileage	136237 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED,FRONT RIGHT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION GETTING FADED RUSTY	الصبغ
01.C Doors	REAR BOTH SIDE REPAINTED,FRONT LEFT REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS RUSTY MUDDY	صدأ
01.E Floor	UNDER FLOOR COVERED MUDDY DIRTY MINOR DENT	الارضية
01.F Bumper	MISALIGN , SCRATCHES	دعامية
01.G Windshield	FRONT COWL PANEL COVER MISSING	زجاج
01.H Vehicle Color	BLACK	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	اخرى

03 Engine Condition

المحرك

03.A Other	INNER COMPARTMENT COVER PART MISSING	اخرى
03.B Engine Visual Condition	REFITTED , ABNORMAL NOISY , KNOCKING PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK , BACK COVER LOOSE	حالة المقاعد
---------------------	----------------------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2021 RIGHT SIDE 2022 EXPIRED GETTING WORN OUT	الاطار الامامي
06.B Rear Tyre	RIGHT SIDE 2022 LEFT SIDE 2020 EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	FRONT MISSING	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنايبر الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	BUSHES DRY CRACK	ازرع
10.B Other	SUSPENSION PARTS REFITTED	اخرى
10.C Ball Joint	BOOT CUT	مفصل كروي
11 Steering Condition		المقود
11.A Steering Boot	BOOT CUT	ربلة المقود
11.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
12 Interior Condition		الحالة الداخليه
12.A Other	CENTER CONSOLE BOX WORN OUT PORTION LOOSE , INTERIOR PARTS GETTING RUSTY	اخرى
12.B AC Condition	NOT COOLING	المكيف
12.C Floor Matting	DIRTY	فرش الأرضيه
12.D Roof Ceiling	FABRIC LOOSE	بطانه السقف
12.E Sun Visor	LEFT SIDE PORTION DAMAGE , RIGHT SIDE LOOSE	حاجب الشمس
12.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
12.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
12.H Engine Start Button	DAMAGE	زر تشغيل المحرك
13 Engine Cooling System		نظام تبريد المحرك
13.A Coolant tank	WATER MIX WITH OIL	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae