CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2392830
Transaction Date	15 May 2026, 14:34:47
Site Name	840 - Emirates Auctions
Transaction Number	28349791 (CC10008) (CC10008)



Vehicle Details

Chassis Number	2G1155S35G*******
Specification	GCC Specification
Make	Chevrolet
Model	Impala
Model Year	2016
Color	Silver
Mileage	158876 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR LEFT SIDE REPAINTED, PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES,PORTION RUSTY	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED, PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	PORTION DENT,FLOOR COVER MISSING	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED	دعامية
01.G Windshield	FRONT CRACK	زجاج
01.H Trunk	REPAINTED, PORTION REPAIRED,REFITTED	صندوق
01.I Door Handle &Lock	FRONT LEFT SIDE OUTER LOCK COVER MISSING	مقابض الأبواب والأقفال
01.J Sign of back accident		وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA /OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	CRACK	كرسي
03.B Engine Visual Condition	MINOR OIL LEAK ,PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Gear Box Mount	CRACK	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	BOTTLE CAP MISSING	ازرع المساحات والشفرات
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE NOT WORKING	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
10 Interior Condition		الحاله الداخليه
10.A AC Condition	OK	المكيف
10.B Audio	PORTION FADED	صوتيات
10.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.D Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae