



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>26 Jan 2023, 15:35:29</b>
Transaction Number	<b>60340378 (CC10009)</b>	Queue Number	<b>664265</b>



Chassis Number	<b>WDDHF5FB0GB232643</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>E 300</b>
Model Year	<b>2016</b>
Color	<b>Silver</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Odometer reading	NOT CHECKED	قراءة عداد المسافات
01.B AC Condition	NOT CHECKED	المكيف
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING,MINOR OIL LEAK	حالة المحرك النظري
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
<b>04 Chassis Condition</b>		<b>الشاسي</b>
04.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
04.B Chassis Number	VIN CHECKED ON STICKER ONLY	رقم القاعدة
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
05.C Visual Gear Box Condition	NOT CHECKED/MINOR OIL LEAK	حالة الجير النظري

DEFECT	REMARKS	
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSHES CUT	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية
07.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
07.C Bumper	MISALIGN	دعامية
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.