CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2966860
Transaction Date	10 Nov 2026, 11:53:20
Site Name	840 - Emirates Auctions
Transaction Number	77747926 (CC10008) (CC10011)



Vehicle Details

Chassis Number	MMBXTA03AE*******
Specification	GCC Specification
Make	Mitsubishi
Model	Mirage
Model Year	2014
Color	Silver
Mileage	193158 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	3

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED GETTING RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Bumper	MISALIGN PORTION CRACK	دعامية
01.E Windshield	SPOT CRACK	زجاج
01.F Bonnet	REFITTED	غطاء المحرك
01.G Trunk	LUGGAGE SHADE,COMPARTMENT COVER MISSING	صندوق
01.H Sign of front accident	FRONT ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK ,COMPONENTS REFITTED,PARTS GETTING RUSTY ,SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED,EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	PARTS GETTING RUSTY ,FLY WHEEL COVER MISSING	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2023 CRACKED,RIGHT	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2019 CRACK EXPIRED,RIGHT	الاطار الخلفي
06.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Tail Light	RIGHT SIDE NOT WORKING	الضوء الخلفي
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.C Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY ,BRAKE WEAK	دواسة الفرامل
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B Mirror	CENTER VIEW MIRROR GETTING FADED,RIGHT SIDE COVER PORTION CRACK	المرايا
11.C AC Condition	NO COOLING	المكيف
11.D Audio	STEREO PANEL PORTION CRACKED	صوتيات
11.E Roof Ceiling	PORTION DIRTY	بطانه السقف
11.F Odometer reading	CLUSTER COVER GETTING FADED	قراءة عداد المسافات
11.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae