



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	01 Nov 2021, 17:48:39
Transaction Number	65372840 (CC10006)	Queue Number	312309



Chassis Number	3N1BCA71BL368729
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Tiida
Model Year	2011
Color	White
Mileage	525846 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED	الصبغ
01.B Doors	LEFT SIDE DOOR REPAINTED,PORTION REPAIRED	أبواب
01.C Fenders	FRONT LEFT&REAR BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
01.D Bonnet	REPAINTED,PORTION REPAIRED	غطاء المحرك
01.E Trunk	REPAINTED,PORTION REPAIRED&NISSAN LOGO MISSING	صندوق
01.F Floor	REAR COMPARTMENT ,QUATAR PANEL BACK PANEL ,CROSS MEMBER REPAIRED	الارضية
01.G Other	REAR QUATER PANEL ,FLOOR HAVE DENT	اخرى
01.H Pillars	LEFT SIDE B/C PILLAR REPAIRED	القوائم
01.I Bumper	REPAINTED	دعامية
01.J Rusty	UNDER BODY PARTS GETTING MINOR RUSTY	صدأ
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
03 Interior Condition		الحالة الداخليه

DEFECT	REMARKS	
03.A Dash Board	DASHBAORD BROKEN	لوحة القيادة
03.B Odometer reading	525847 KM	قراءة عداد المسافات
03.C AC Condition	VKENT GRILL ADJUSTMENT NOT WORKING & BLOWER FAN NOISY	المكيف
03.D Door Panel	WORNOUT	لوحة بطانة الباب
03.E Steering Wheel and control buttons	WORNOUT	عجلة القيادة وازرار التحكم
03.F Other	HAND REST COVER DAMAGED	اخرى
03.G Roof Ceiling	LOOSE	بطانه السقف
04 Lights		الاضاءة
04.A Head Light	RIGHT BULB LOOSE NOT FIX	الاضاءة الرئيسية
04.B Tail Light	FRONT BOTH PARK LIGHT & REAR RIGHT TAIL LIGHT NOT WORKING	الانارة
05 Brake Condition		الفرامل
05.A Brake Pedal	BRAKE PADEL SPONGY	دواسة الفرامل
06 Chassis Condition		الشاصي
06.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION MINOR BEND	الشاسيه
07 Exhaust System		نظام العادم
07.A Other	EXHAUST PIPE LEAK	اخرى
08 Engine Condition		المحرك
08.A Engine Condition	OIL LEAK	حالة المحرك
08.B Smoke	BLACK	دخان
09 Transmission Condition		الجير
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Gear Box	OK	الجير
10 Seats Condition		المقاعد
10.A Seat Belt	OK	حزام الأمان
10.B Seat Condition	OK	حالة المقاعد
11 Wipers and Arms		المساحات
11.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	CAP MISSING	خزان التبريد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.



- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

Test Certificate



Vehicle
Registration



X FAILED

Change possession :	65560934
Chassis No :	3N1BC1A71BL368729
Vehicle Make :	NISSAN
Vehicle Model :	TIIDA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	525847 Kms.
Origin :	Mexico
Model Year :	2011
Gear Type :	--
Engine Size :	3500 CC
Engine No :	MR18-5721...
Horse Power :	123
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1200 Kgs. 1600 Kgs.

Certificate Number :	5-TAS-2021-15400190
Inspection Date :	07-11-2021
Certificate Print Date :	25-11-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	13 min 18 sec
Appointment Ref Number :	--
Start Time :	10:11
End Time :	10:24
Lane :	02
Token No. :	108
Attempt :	1
Prints No :	2

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
1 %	12 %	1 %	0 %
Vehicle on Petrol HC Reading			
5 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Stop lamps CHANGE RIGHT SIDE BULB	Bulb busted	Major
Spare Tire KEEP PROPER PLACE	Missing (Major)	Major
Engine REPAIR AND CLEAN ENGINE OIL LEAKING	Oil leaking continuously	Major
Park and Tail lamps CHANGE FRONT BOTH SIDE PARK LIGHT BULB	Bulb busted	Major
Dip beams(Low Beams) headlight CHANGE RIGHT SIDE BULB	Busted bulb	Major
Warning triangle	Missing	Major
Tire CHANGE REAR RIGHT SIDE TIRE INNER SIDE WORN OUT	Uneven wear	Major
Pedal REPAIR BREAK PEDAL SPONGY	Hard/spongy	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	1800	

Inspection Remarks:

MINOR DENTS & SCRATCHES ON BODY ,REAR COMPARTMENT , LOWER BACK PANEL REAR BUMPER TAIL DOOR REPAIRED ,FRONT BUMPER SUPPORT ,BUMPER,LEFT SIDE FENDER BOTH SIDE QUARTER PANEL REPAIRED

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
33706	Cash	15400190	AED 170 Collected on 07/11/2021
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Sittu Paloth Sreesan Paloth

i This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.



❗ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.