

Queue Number

2873174

Transaction Date

15 Oct 2026, 14:55:25

Site Name

840 - Emirates Auctions

Transaction Number

47380685 (CC10008) (CC10025)



Vehicle Details

Chassis Number	JTEHJ09J56*****
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser
Model Year	2006
Color	Silver
Mileage	302304 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES , PORTION FADED	الصبغ
01.C Doors	REAR RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Pillars	RIGHT SIDE B/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.F Sign of front accident	FRONT BUMPER FRAME BEND	وجود مؤشر لحادث في المقدمة
01.G Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME THICK RUSTPROOFED PORTION GETTING RUSTY, FRONT BOTH SIDE CHASSIS END BRACKET BEND	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED .OIL WET ,ABNORMAL NOISY	الحالة النظرية للمحرك
------------------------------	-----------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	OPEN,REFITTED	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT ,SCRATCHES ,FRONT BOTH SIDE HUB COVER MISSING	حالة الجنوط
06 Interior Condition		الحالة الداخلية
06.A Other	CENTER CONSOLE BOX COVER WORN OUT , INTERIOR PARTS GETTING RUSTY	اخرى
06.B Mirror	LEFT SIDE MIRROR ADJUST MENT NOT WORKING PROPERLY , CENTER MIRROR PORTION LOOSE	المرآيا
06.C AC Condition	OK	المكيف
06.D Floor Matting	EXTRA PLASTIC MATTING	فرش الأرضية
06.E Audio	CENTER FRAME PORTION LOOSE	صوتيات
06.F Roof Ceiling	PORTION LOOSE	بطانة السقف
06.G Door Panel	WORN OUT , PORTION DAMAGED	لوحة بطانة الباب
06.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae