

Queue Number

2905902

Transaction Date

26 Oct 2026, 11:16:36

Site Name

840 - Emirates Auctions

Transaction Number

58771599 (CC10010) (CC10011)



Vehicle Details

Chassis Number

MZBEP8144P*****

Specification

GCC Specification

Make

Kia

Model

SELTOS

Model Year

2023

Color

Grey

Mileage

21025 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	MINOR DENT SCRATCHES ON BODY	الصبغ
01.B Floor	UNDER FLOOR POWERTRAIN SUSPESION ,RUNNIG PARTS GETTING RUSTY ,SIG N OF FLOODED.	الارضية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	COMPONENT PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	-------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	COMPONENT PARTS RUSTY.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي

06 Lights

الاضاءة

06.A Head Light	LENS FADED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER.	ضوء تحذير

Condition	Remarks	الحالة
07 Interior Condition		الحاله الداخليه
07.A AC Condition	OK	المكيف
07.B Engine Start Button	REMOTE PORTION DAMAGED	زر تشغيل المحرك
08 Battery Condition		حالة البطارية
08.A Battery Condition	WEAK ,DISCHARGED ,	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae