

Queue Number

2891653

Transaction Date

21 Oct 2026, 16:44:36

Site Name

840 - Emirates Auctions

Transaction Number

57453124 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1C4HJXDNOM*****
Specification	Imported
Make	Jeep
Model	Wrangler
Model Year	2021
Color	Black
Mileage	150741 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	LEFT SIDE RUNNING BOARD MOUNT SIGN OF ALIGN REPAIRED	الارضية
01.D Pillars	RIGHT SIDE C/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.E Trunk	REFITTED	صندوق
01.F Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.G Sign of back accident	BACK PANEL QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED, BEND	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Belt	FRONT BOTH SIDE & REAR RIGHT SIDE NOT WORKING	حزام الأمان
04.B Seat Condition	DRIVER SEAT COVER PORTION CRACKED	حالة المقاعد

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY	الحالة النظرية للجير
--------------------------------	---------------------------------------	----------------------

Condition	Remarks	الحالة
05.B DIFFERENTIAL	FRONT DIFFERENTIAL ASSEMBLY REPAIRED, CRACKED	الدفرنش
05.C Road Test	NOT CHECKED	فحص علي الطريق
05.D Four Wheel Drive	UNSAFE TO CONNECT 4X4	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	BOTH SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
07.B Indicator & Hazard light	FRONT LEFT SIDE COVER CRACKED	الاشارة
07.C Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	FRONT BEND	ممتص الصدمات ازرع اخرى
08.B Shock Absorber	FRONT LEFT SIDE BEND	
08.C Arms	FRONT LEFT SIDE CONTROL ARM REPAIRED & MOUNT BEND	
08.D Other	SUSPENSION MISALIGN	
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	CENTER MIRROR PORTION FADED	المرايا
09.C AC Condition	OK	المكيف
09.D Sun Visor	RIGHT SIDE LIGHT MIRROR NOT WORKING	حاجب الشمس

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae