CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934055
Transaction Date	03 Nov 2026, 17:00:05
Site Name	840 - Emirates Auctions
Transaction Number	95528100 (CC10026) (CC10026)



Vehicle Details

Chassis Number	WDD2130641*******
Specification	Imported
Make	Mercedes
Model	E 43
Model Year	2001
Color	White
Mileage	111199 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	BOTH RIGHT SIDE POTION REPAINTED & FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , MINOR DENT SCRATCHES	الصبغ
01.C Doors	BOTH RIGHT SIDE POTION REPAINTED	أبواب
01.D Floor	UNDER FLOOR, ENGINE , GEAR COVERED , CHECK VISIBLE AREA ONLY	الارضية
01.E Bonnet	STAY SHOCK WEAK	غطاء المحرك
01.F Door Handle &Lock	FRONT LEFT SIDE OUTER LOCK COVER DAMAGE	مقابض الأبواب والأقفال
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS FULLY COVERED , CHECK VISIBLE AREA ONLY	الشاسيه
02.B Other	NEED TO REMOVE BOTH SIDE INNER FENDER COVER & ENGINE UNDER COVER FOR PROPER INSPECTION	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OK	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	OK	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06.D Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	BODY LOW LEVEL	ممتص الصدمات
09 Steering Condition		المقود
09.A Axle	BOOT CRACK	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE PANEL PORTION WORN OUT	اخري
10.B AC Condition	OK	المكيف
10.C Dash Board	GLOVE BOX PORTION WORN OUT	لوحة القياده
10.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae