CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3004181
Transaction Date	18 Nov 2026, 16:41:34
Site Name	840 - Emirates Auctions
Transaction Number	60150304 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WBAKU6102F*******
Specification	GCC Specification
Make	BMW
Model	X6
Model Year	2015
Color	White
Mileage	399901 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE FIBER PAINT CANNOT CHECKED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS NOT VISIBLE COVERED MUDDY , REQUIRED STEAM WASH	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Windshield	FRONT SPOT CRACK	زجاج
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED & MUDDY CHECK VISIBLE AREA ONLY /OK	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE SMOKE	دخان
03.B Engine Visual Condition	MINOR OIL LEAK OPEN REFITTED SHAKING GETTING RUSTY,	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT BOTH SIDE SEAT BACK COVER PORTION DAMAGED,LOOSE	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	DENT	اخري
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	OPEN REFITTED JERKING GETTING RUSTY, BOLT LOOSE	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Brake Condition		الفرامل
09.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	BUSHES CUT	ازرع
10.B Other	SUSPENSION REFITTED	اخري
11 Interior Condition		الحاله الداخليه
11.A Other	TEA CUP SLIIDIN COVER DAMAGED & CENTER CONSOLE BOX PORTION WORN OUT	اخري
11.B Mirror	LEFT SIDE COVER MIRROR PORTION DAMAGED	المرايا
11.C AC Condition	OK	المكيف
11.D Dash Board	LEATHER WORN OUT LOOSE	لوحة القياده
11.E Roof Ceiling	PORTION LOOSE	بطانه السقف
11.F Door Panel	PORTION WORN OUT MELTED	لوحة بطانة الباب
11.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae