



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 Jun 2022, 17:44:23
Transaction Number	57312178 (CC10006)	Queue Number	312309



Chassis Number	WP1ZZZ9PZ9LA46368
Engine Number	
Vehicle Class	Car
Manufacturer	Porsche
Model	Cayenne
Model Year	2009
Color	White
Mileage	162338 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
01.B Road Test	NOT CHECK	فحص علي الطريق
02 Chassis Condition		الشاسيه
02.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
03 Body		جسم المركبة
03.A Floor	UNDER FLOOR COVERED , CHECKED VISIBLE AREA ONLY	الارضيه
03.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
03.C Fenders	PORTION REPAIRED, REPAINTED	مدكار
03.D Doors	PORTION REPAINTED	أبواب
04 Interior Condition		الحاله الداخليه
04.A AC Condition	OK	المكيف
04.B Roof Ceiling	LOOSE	بطانه السقف
04.C Other	REAR CIGARETTES BOX NOT CLOSING	اخرى
05 Engine Condition		المحرك

DEFECT	REMARKS	
05.A Visual Engine Condition	OIL LEAK	حالة المحرك النظري
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.