

Queue Number 2906020

Transaction Date 26 Oct 2026, 12:51:21

Site Name
840 - Emirates AuctionsTransaction Number
22194587 (CC10021) (CC10021)

Vehicle Details

Chassis Number	WAUAF8K7B*****
Specification	GCC Specification
Make	Audi
Model	A4
Model Year	2011
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED,PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERED,PORTION DENTS, MUDDY,CHECKED VISIBLE AREA ONLY	الارضية
01.D Bumper	MISALIGN , PORTION SCRATCHES , TOW HOOK COVER MISSING	دعامية

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA ONLY PORTION DENT	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED PARTS REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition الجير

04.A Gear Box Visual Condition	NOT CHECKED PARTS REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition الاطارات

05.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط

Condition	Remarks	الحالة
06 Lights الاضاءة		
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07 Brake Condition الفرامل		
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Suspension System ممتص الصدمات		
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition الحالة الداخليه		
09.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	CENTER VIEW MIRROR BACK COVER DAMAGE	المرايا
09.C AC Condition	NOT CHECK	المكيف
09.D Dash Board	PORTION WORN OUT	لوحة القيادة
09.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.G Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT & DUST COVER DAMAGE	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae