

#### **TEST CERTIFICATE**

Site Number Transaction Number **840-Emirates Auctions** 30439299 (CC10009)

Transaction Date Oueue Number

17 Nov 2022, 16:15:35

624687

Chassis Number

JN8AY2NY3E9067545

**Engine Number** 

Vehicle Class

Car

Manufacturer

Nissan

Model

**Patrol** 

Model Year

2014

Color

White

Mileage

92064 Km

Fuel Type

**Petrol** 

No. Of Cylinders

Specification

**GCC Specification** 

**REMARKS DEFECT** 

Of Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف

01.A AC Condition 01.B Steering Wheel and

control buttons

02.C Smoke

03.C Road Test

WORN OUT,

عجلة القيادة وازرار التحكم

المكيف

دخان

فحص علي الطريق

مفصل کروی

**02 Engine Condition** المحرك

MINOR OIL LEAK **02.A Visual Engine Condition** حالة المحرك النظرى MOUNT RUBBER CRACKED 02.B Mount كرسي

**BLACK SMOKE** 

**03 Transmission Condition** الجير

03.A Visual Gear Box SIGN OF MINOR OIL LEAK حالة الجير النظرى Condition

03.B Gear Box Mount MOUNT RUBBER CRACKED كرسى الجير

**04 Suspension System** ممتص الصدمات

NOT CHECK

04.A Ball Joint **BOOT CUT** 

04.B Arms LOWER ARM BUSHES CRACKED ازرع

04.C Shock Absorber **LEAK** ممتص الصدمات

DEFECT	REMARKS	
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودات
05.B Axle	LEAK	اكسلات
06 Chassis Condition		الشاصي
06.A Chassis	FRONT RIGHT SIDE CHASSIS & REAR LOWER BRACKET REPAIRED, GETTING RUSTY	الشاسيه
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
08 Tires and Rims Condition		الاطارات
08.A Rear Tyre	BOTH SIDE 2020 CRACKED,	الاطار الخلفي
08.B Front Tyre	BOTH SIDE 2021,	الاطار الامامي
09 Body		جسم المركبة
09.A Paint	BODY MINOR DENT, SCRATCHES	الصبغ
09.B Rusty	UNDER FLOOR PARTS CHASSIS RUSTY	صدأ

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

## **Test Certificate**









Plate Details:		
Chassis No:	JN8AY2NY3E9067545	
Vehicle Make :	NISSAN	
Vehicle Model:	PATROL	
Vehicle Class:	Light Vehicle	
Body Type:	STATION	
Fuel:	Benzene	
Color:	White	
Drive Direction:		
Dimensions : (H x W x L)	xx	
Current Odometer :	92065 Kms.	
Origin: Japan	Model Year: 2014	
Gear Type: Automatic	Engine Size: 3500 CC	
Engine No: VK56107833A	Horse 400	
Axles No: 2	Power:	
No Of 4	Cylinders: 8	
Doors :	No Of Seats: 8	
<b>G. V. W.:</b> 3500 Kgs.	Empty 2845 Kgs.	
	Weight:	

Certificate Number: 5-TAS-2022-18178725 Inspection Date: 25-11-2022 Certificate Print Date : 25-11-2022 Services: Registration Test Vehicle Testing Partner: Tasieel Vehicle Testing Center: Tasjeel Al Aweer Total Time Taken: 10 min 15 sec **Appointment Ref** Number: Start 9:40 **End Time:** 9:51 Time: Token No.: 108 Lane: 03 Prints No: 1 Attempt: 1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)



Distance per year Fuel consumed per year



18 AED
Fuel cost per year

O.1 ton
Carbon footprint
per year

#### **Parameter Readings**

Service brake imbalance on front axle  $26\,\%$ 

Service brake imbalance on rear axle 29 %

Parking brake imbalance between LHS and RHS 34 % Vehicle on Petrol CO Reading 0.1 %

# Vehicle on Petrol HC Reading

43 PPM VOL

## **Inspection Findings**

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	5600	

#### **Inspection Remarks:**

FRONT RISGHT LOWER CHASSIS&JACK MOUNTING REPAIRED/FRONT BUMPER REPAIRED/ MINOR BODY DENT/ SCRATCHES&MINOR ENGINE OIL LEAK/

### **Payment Details**

 Inspection Performed by
 Payment Method
 Transaction Number
 Service Fees

 3104
 Cash
 18178725
 AED 170 Collected on 25/11/2022

 Parking Slot No
 Service Name
 Attempt
 Received by

 - Registration Test
 1
 Malek Tayseer Mustafa Othman

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
  تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
  ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
  30.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.