

TEST CERTIFICATE

Site Number
Transaction Number

05.A Shock Absorber

840-Emirates Auctions 64818198 (CC10008) Transaction Date

21 Jun 2022, 17:57:58

Queue Number

312309

Chassis Number

3N1BC1CP5BL379441

Engine Number

Vehicle Class

Manufacturer Nissan

Model

Model Year

Color

White

Versa

2011

Car

Mileage

104094 Miles

Fuel Type

Petrol

No. Of Cylinders
Specification

USA Imported

ممتص الصدمات

DEFECT REMARKS

01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
01.B Rims Condition	RIMS HAVE DENT SCRATCHES	حالة الجنوط
01.C Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
02 Chassis Condition		الشاصي
02.A Chassis	REAR BOTH SIDE CHASSIS REPAIRED	الشاسيه
03 Body		جسم المركبة
03.A Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT ,SCRATCHES	الصبغ
03.B Fenders	FRONT RIGHT SIDE REFITTED	مدكار
04 Interior Condition		الحاله الداخليه
04.A AC Condition	NOT COOLING	المكيف
04.B Door Panel	PORTION LOOSE, DAMAGED	لوحة بطانة الباب
04.C Roof Light	NOT WORKING	أنارة السقف
05 Suspension System		ممتص الصدمات

SHOCK ABSORBER LEAK

DEFECT	REMARKS	
05.B Ball Joint	воот сит	مفصل کروي
05.C Other	STABLIZER LINK BOOT CUT	اخري
05.D Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL LEAK, SHAKING	حالة المحرك النظرى
06.B Mount	MOUNT RUBBER CRACKED	كرسي
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودات
08 Transmission Condition		الجير
08.A Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظرى
08.B Road Test	NOT CHECK	فحص علي الطريق

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير سارى.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.