

Queue Number	2899775	Transaction Date	23 Oct 2026, 16:49:36
Site Name	840 - Emirates Auctions	Transaction Number	80538507 (CC10021) (CC10021)



Vehicle Details

Chassis Number	WDDHF5FB4G*****
Specification	Imported
Make	Mercedes
Model	E 500
Model Year	2016
Color	White
Mileage	137894 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	REMOVE BOTH SIDE FENDER INNER COVER FOR PROPER INSPECTION	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.E Bonnet	EMBLEM MISSING	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FULLY COVERED , CHECK VISIBLE AREA ONLY , PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Other	LEFT SIDE AIR FILTER HOSE DAMAGE	اخرى
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACK & BACK POCKET LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Steering Box	MINOR OIL LEAK	جهاز المقود
10.B Tie Rod End	BOOT CRACK	مؤخرة الرودادات
10.C Axle	BOOT CRACK	اكسلات
11 Interior Condition		الحالة الداخلية
11.A AC Condition	NOT CHECK	المكيف
11.B Dash Board	PORTION WORN OUT	لوحة القيادة
11.C Roof Ceiling	PORTION WORN OUT	بطانه السقف
11.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae