



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>28 Apr 2022, 14:46:49</b> |
| Transaction Number | <b>73759492 (CC10006)</b>    | Queue Number     | <b>312309</b>                |



|                  |                          |
|------------------|--------------------------|
| Chassis Number   | <b>WPOZZZ97ZAL044116</b> |
| Engine Number    |                          |
| Vehicle Class    | <b>Car</b>               |
| Manufacturer     | <b>Porsche</b>           |
| Model            | <b>Panamera</b>          |
| Model Year       | <b>2010</b>              |
| Color            | <b>White</b>             |
| Mileage          | <b>167440 Km</b>         |
| Fuel Type        | <b>Petrol</b>            |
| No. Of Cylinders | <b>8</b>                 |
| Specification    | <b>GCC Specification</b> |

| DEFECT                             | REMARKS  |                        |
|------------------------------------|--|------------------------|
| <b>01 Body</b>                     |  | <b>جسم المركبة</b>     |
| 01.A Fenders                       | LEFT SIDE BOTH PORTION REPAIRED,REPAINTED                    | مدكار                  |
| 01.B Doors                         | LEFT SIDE BOTH PORTION REPAIRED,REPAINTED                    | أبواب                  |
| 01.C Paint                         | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES | الصبغ                  |
| 01.D Floor                         | UNDER BODY FULLY COVERD                                      | الارضية                |
| 01.E Pillars                       | LEFT SIDE P/ PILLAR INNER COVER LOOSE                        | القوائم                |
| <b>02 Interior Condition</b>       |  | <b>الحاله الداخليه</b> |
| 02.A AC Condition                  | OK   | المكيف                 |
| 02.B Roof Ceiling                  | PORTION LOOSE  | بطانه السقف            |
| <b>03 Tires and Rims Condition</b> |  | <b>الاطارات</b>        |
| 03.A Front Tyre                    | BOTH SIDE 2021   | الاطار الامامي         |
| 03.B Rear Tyre                     | BOTH SIDE 2021   | الاطار الخلفي          |
| <b>04 Chassis Condition</b>        |  | <b>الشاصي</b>          |
| 04.A Chassis                       | VISABLE AREA OK  | الشاسيه                |
| <b>05 Transmission Condition</b>   |  | <b>الجير</b>           |

## DEFECT

## REMARKS

05.A Road Test

NOT CHECK

فحص علي الطريق

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.