CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899410
Transaction Date	22 Oct 2026, 17:01:46
Site Name	840 - Emirates Auctions
Transaction Number	74319971 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WBAFR710XD*******
Specification	GCC Specification
Make	BMW
Model	535 i
Model Year	2013
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR LEFT SIDE QUARTER PANEL REPAIRED REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH DOORS NOT OPEN	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN ,SCRATCHES .	دعامية
01.G Trunk	NOT OPEN	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	NEED TO REMOVE FENDER UNDER COVER FOR INSPECTION .	اخري
02.C Chassis Number	VIN CHECKED ONLY APRON , STICKER NOT CHECKED.	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	EXPIRED CRACKED. DAMAGED	الاطار الامامي
05.B Rear Tyre	EXPIRED CRACKED DAMAGED	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK.,	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B AC Condition	NOT CHECKED ,GRILL PORTION LOOSE	المكيف
10.C FLoor Matting	CENTER CONSOLE SIDE STRIP LOOSE.	فرش الأرضيه
10.D Dash Board	PORTION LOOSE	لوحة القياده
10.E Roof Ceiling	PORTION LOOSE	بطانه السقف
10.F Odometer reading	NOT CHECKED. .	قراءة عداد المسافات
10.G Door Panel	WORNO UT PORTION LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae