CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877761
Transaction Date	20 Oct 2026, 11:27:15
Site Name	840 - Emirates Auctions
Transaction Number	36893622 (CC10026) (CC10026)



Vehicle Details

Chassis Number	1N4BL24E79*******
Specification	GCC Specification
Make	Nissan
Model	Altima
Model Year	2009
Color	Black
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOT SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR THICK RUST PROOVED PORTION DENTS, MUDDY	الارضية
01.E Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.F Bonnet	REFITTED , MISALIGN	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION COVER , CHECK VISIBLE AREA GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2016 EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE DAMAGE	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C FLoor Matting	DIRTY	فرش الأرضيه
09.D Dash Board	DAMAGE	لوحة القياده
09.E Odometer reading	NOT CHECK	قراءة عداد المسافات
09.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.G Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	PORTION WORN OUT , SHIFTER COVER MISING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae