

Queue Number 2852659

Transaction Date 09 Oct 2026, 16:35:57

Site Name
840 - Emirates AuctionsTransaction Number
60692190 (CC10013) (CC10025)

Vehicle Details

Chassis Number 1C4RJKBG0N*****
 Specification GCC Specification
 Make Jeep
 Model Grand Cherokee
 Model Year 2022
 Color Grey
 Mileage 81014 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES	الصيغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION COVERED DIRTY MUDDY	الارضية
01.E Bumper	MISALIGN HOOK COVER MISSING	دعامية
01.F Bonnet	PORTION DENTS	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COVERED PORTION GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	UPPER COVER MISSING	اخرى
03.B Engine Visual Condition	OPEN REFITTED , PARTS GETTING RUSTY , ABNORMAL NOISY	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT RIGHT SIDE COVER PORTION LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B DIFFERENTIAL	FRONT HOUSING PORTION DAMAGED	الدفرنشيل

Condition	Remarks	الحالة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	NOT WORKING	الاضاءة الرئيسية
07.B Indicator & Hazard light	FRONT NOT WORKING	الاشارات
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.D Fog light	NOT WORKING	كشف الضباب
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	ARM DENT BUSHES DRY CRACK	ازرع
09.B Other	SUSPENSION PARTS REFITTED	اخرى
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY / WATER FLOODED VEHICLE	اخرى
10.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING	المرآيا
10.C AC Condition	NOT COOLING	المكيف
10.D Power Window Switch And Glass	FRONT RIGHT SIDE & REAR BOTH SIDE NOT WORKING	مفتاح النافذه و الزجاج
10.E Steering Wheel and control buttons	ADJUSTMENT NOT WORKING	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carscheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carscheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

