CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2920097
Transaction Date	29 Oct 2026, 13:22:50
Site Name	840 - Emirates Auctions
Transaction Number	85836363 (CC10009) (CC10012)



Vehicle Details

Chassis Number	5N1AR2M55G*******
Specification	Imported
Make	Nissan
Model	Pathfinder
Model Year	2016
Color	White
Mileage	180469 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS FULLY MUDDY PORTION DENT	الارضية
01.F Bonnet	REPAINTED , REFITTED	غطاء المحرك
01.G Trunk	MISALIGN , BUTTON LOOSE	صندوق
01.H Sign of front accident	FRONT BUMPER BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED MUDDY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Chassis Number	MANUFACTUR STICKER MISSING	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL WET REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	REFITTED GETTING RUSTY DELAY SHIFTTING,GT NOISY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

CAR CHECK

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
05.C Rims Condition	LEFT SIDE HUB COVER MISSING	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودات
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS RUSTY , (SING OF FLOODED) , INTERIOR REFITTED	اخري
08.B Roof Ceiling	REPLACED	بطانه السقف
08.C Sun Visor	LEFT SIDE STAND MISSING	حاجب الشمس
08.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09 Battery Condition		حالة البطارية
09.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae