CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2890791
Transaction Date	20 Oct 2026, 16:41:12
Site Name	840 - Emirates Auctions
Transaction Number	67022147 (CC10013) (CC10025)



Vehicle Details

Chassis Number	5N1AR1N8XC*******
Specification	GCC Specification
Make	Nissan
Model	Pathfinder
Model Year	2012
Color	Grey
Mileage	330802 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION GETTING FADED	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR DIRTY MUDDY PORTION MINOR DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	REPAINTED	السقف
01.H Trunk	REPAINTED PORTION REPAIRED REFITTED	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME DIRTY PORTION GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	OPEN REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Belt	REAR LEFT SIDE PART COVER MISSING	حزام الأمان
04.B Seat Condition	DRIVER SEAT EXTRA COVER PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
07 Steering Condition		المقود
07.A Steering Boot	BOOT CUT	ربلة المقود
07.B Tie Rod End	BOOT CUT	مؤخرة الرودات
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE BOX LEATHER PORTION DAMAGED , LOCK COVER DAMAGED (INTERIOR PARTS GETTING RUSTY)	اخري
08.B Mirror	CENTER MIRROR GETTING FADED	المرايا
08.C AC Condition	OK	المكيف
08.D Dash Board	EXTRA COVER	لوحة القياده
08.E Roof Ceiling	PORTION CUT	بطانه السقف
08.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae