



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>31 Oct 2021, 12:03:18</b>
Transaction Number	<b>20695670 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WDB2112701A689780</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>E 500 AMG</b>
Model Year	<b>2005</b>
Color	<b>Silver</b>
Mileage	<b>0</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH 2020	الاطار الامامي
01.B Rear Tyre	BOTH 2020	الاطار الخلفي
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Bonnet	REAR TRUNK CLOSING MACHINE NOISY	غطاء المحرك
02.B Paint	BODY PORTION REPAINTED	الصبغ
02.C Roof	ROOF PORTION REPAINTED	السقف
02.D Doors	CONSOLE BOX DAMAGED,MISSING	أبواب
<b>03 Interior Condition</b>		<b>الحالة الداخليه</b>
03.A Other	CONSOLE BOX DAMAGED&ROOF CEILING LOSE	اخرى
03.B AC Condition	NOT WORKING	المكيف
03.C Odometer reading	183573 KM	قراءة عداد المسافات
<b>04 Wipers and Arms</b>		<b>المساحات</b>
04.A Other	WORN OUT&RIGHT NOT WORKING	اخرى
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Warning Light	WARRING ON IN DISPLAY	ضوء تحذير
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Shock Absorber	LEAK	ممتص الصدمات
06.B Arms	FRONT LOWER ARMS BUSHES CUT	ازرع

DEFECT	REMARKS	
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Axle	REAR AXLE BOOT CUT	اكسلات
07.B Steering Box	POWER STEERING HARD	جهاز المقود
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Gear Box	OK	الجير
08.B Propeller Shaft	POPELLAR SHAFT RUBBER CRACKED	ناقل الحركة
08.C Road Test	NOT CHECK	فحص علي الطريق
<b>09 Exhaust System</b>		<b>نظام العادم</b>
09.A Other	GETTING MINOR RUSTY,PIPE WELDED	اخرى
<b>10 Chassis Condition</b>		<b>الشاصي</b>
10.A Chassis	OK	الشاسيه
<b>11 Engine Condition</b>		<b>المحرك</b>
11.A Engine Condition	OIL LEAK&RADIATOR WATER TANK MINOR LEAK	حالة المحرك
11.B Other	AIR FLTER INTAK PIPE CUT	اخرى
<b>12 Seats Condition</b>		<b>المقاعد</b>
12.A Seat Condition	HEAD REST LEATHER DAMAGED&RIGHT AUTO,SEAT NOT WORKING PROPERLY &BOTTON MISSING	حالة المقاعد
12.B Seat Belt	OK	حزام الأمان

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.