



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Jan 2023, 13:42:34
Transaction Number	27242539 (CC10010)	Queue Number	657701



Chassis Number	1N4AL2A9XAC134668
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Altima 2.5S
Model Year	2010
Color	--
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
02 Tires and Rims Condition		الاطارات
02.A Rear Tyre	BOTH SIDE 2021 CRACKED	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2021 CRACKED,PUNCTURE	الاطار الامامي
03 Body		جسم المركبة
03.A Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
03.B Bumper	MISALIGN	دعامية
03.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
03.D Floor	PORTION DENT	الارضية
03.E Vehicle Color	PEACH	لون المركبة
04 Suspension System		ممتص الصدمات
04.A Arms	LOWER ARM BUSH CUT	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
05 Steering Condition		المقود

DEFECT	REMARKS	
05.A Steering Oil	OIL LEAK	زيت المقود
05.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
06 Interior Condition		الحاله الداخليه
06.A Odometer reading	NOT CHECK	قراءة عداد المسافات
06.B Dash Board	PORTION CRACKED	لوحة القيادة
06.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
06.D Door Panel	PORTION DAMAGED	لوحة بطانة الباب
06.E AC Condition	NOT CHECK	المكيف
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Visual Gear Box Condition	NOT CHECK,OIL LEAK REFITTED	حالة الجير النظري
08 Engine Condition		المحرك
08.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,OIL LEAK ,REFITTED	حالة المحرك النظري
09 Seats Condition		المقاعد
09.A Seat Condition	EXTRA COVER	حالة المقاعد
10 Chassis Condition		الشاصي
10.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.