



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>28 Apr 2022, 11:55:45</b>
Transaction Number	<b>77468860 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WDD2211711A178296</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>S 550</b>
Model Year	<b>2008</b>
Color	<b>White</b>
Mileage	<b>229787 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>Japan Imported</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT RIGHT SIDE & REAR LEFT SIDE PORTION REPAIRED,REPAINTED & REAR RIGHT SIDE REPAIRED,REPAINTED	مدكار
01.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES	الصبغ
01.C Floor	UNDER BODY FULLY COVERED , CHECKED VISIBLE AREA OK	الارضية
01.D Doors	REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	أبواب
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Road Test	NOT CHECKED	فحص علي الطريق
04.B Visual Gear Box Condition	MINOR OIL LEAK ,	حالة الجير النظري

DEFECT	REMARKS	
<b>05 Chassis Condition</b>		النشاصي
05.A Chassis	CHASSIS COVERED , CHECKED VISIBLE AREA OK	النشاصيه
<b>06 Suspension System</b>		ممتص الصدمات
06.A Ball Joint	BOOT CUT	مفصل كروي
06.B Arms	LOWER ARM BUSHES CRACKED	ازرع
06.C Shock Absorber	CHECKE FRONT LEFT SIDE SHOCK LOWER MOUNT BROKEN	ممتص الصدمات
<b>07 Interior Condition</b>		الحاله الداخليه
07.A AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.