

Queue Number 2672944

Transaction Date 25 Aug 2026, 10:42:29

Site Name
840 - Emirates AuctionsTransaction Number
50683121 (CC10021) (CC10021)

Vehicle Details

Chassis Number	JMYLRV93W9*****
Specification	GCC Specification
Make	Mitsubishi
Model	Pajero
Model Year	2009
Color	--
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED,RUSTY	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR PORTION DENT	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.E Vehicle Color	SILVER	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY GETTING RUSTY PORTION MINOR DENT OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START,ALL SYSTEM NOT CHECK,REFITTED,PARTS GETING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECK,REFITTED,PARTS GETING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي

Condition	Remarks	الحالة
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED,ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS RUSTY,SIGN WATER OF FLOODED	اخرى
08.B AC Condition	NOT CHECK	المكيف
08.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.D Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae