CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899681
Transaction Date	30 Oct 2026, 14:53:57
Site Name	840 - Emirates Auctions
Transaction Number	16813333 (CC10010) (CC10011)



Vehicle Details

Chassis Number	KMHL24JA8N*******
Specification	Imported
Make	Hyundai
Model	Sonata
Model Year	2022
Color	Black
Mileage	224057 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR RIGHT SIDE REPAINTED PORTION REPAIRED,FRONT RIGHT SIDE CHROME LOOSE	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION GETTING FADED RUSTY	الصبغ
01.C Doors	REAR RIGHT SIDE REPLACED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT .	الارضية
01.F Bumper	FRONT DAMAGED	دعامية
01.G Bonnet	MISALIGN	غطاء المحرك
01.H Sign of front accident	FRONT ASSEMBLY REFITTED , RADIATOR SUPPORT BRACKET DENT .	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident	RIGHT SIDE QUARTER PANEL ,WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED ,NOT VISIBLE PROPERLY ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	NEED TO REMOVE FENDER UNDER COVER FOR INSPECTION .	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	COMPONENT PARTS GETTING RUSTY ABNORMAL NOISY .	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	COMPONENT PARTS GETING RUSTY , MINOR JERKING.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Spare Tire &Tools	TOOLS MISSING	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE PORTION DAMAGED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES DRY CRACKED .	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX DAMAGED/INTERIOR PARTS GETTING RUSTY.	اخري
10.B AC Condition	NO COOLING	المكيف
10.C Power Window Switch And Glass	MAIN SWITCH PANEL LOOSE	مفتاح النافذه و الزجاج
10.D Air Bag	STEERING AIR BAG OPEN REFITTED .	وسائد هوائية
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae