



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	13 Jan 2022, 18:07:32
Transaction Number	74588217 (CC10006)	Queue Number	312309



Chassis Number	1GKEV33788J275692
Engine Number	
Vehicle Class	Car
Manufacturer	GMC
Model	Acadia
Model Year	2008
Color	White
Mileage	170455 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Chassis Condition		الشاسي
01.A Chassis	OK	الشاسيه
02 Steering Condition		المقود
02.A Steering Boot	BOOT CUT	ربلة المقود
02.B Steering Oil	MINOR OIL LEAK	زيت المقود
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Gear Box	REFITTED	الجير
04 Suspension System		ممتص الصدمات
04.A Arms	FRONT LOWER ARM BUSH WORN OUT	ازرع
04.B Shock Absorber	REAR LEFT SIDE OIL LEAK	ممتص الصدمات
05 Exhaust System		نظام العادم
05.A Other	LEAK	اخرى
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

DEFECT	REMARKS	
06.B Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
06.C Tail Light	FRONT LEFT SIDE PARK LIGHT NOT WORKING	الانارة
06.D Indicator & Hazard light	FRONT LEFT SIDE INDICATOR NOT WORKING	الاشارات
07 Engine Condition		المحرك
07.A Other	ENGINE UPPER COVER MISSING	اخرى
07.B Engine Condition	REFITTED	حالة المحرك
08 Seats Condition		المقاعد
08.A Seat Condition	FONT LEFT SIDE DAMAGED	حالة المقاعد
08.B Seat Belt	OK	حزام الأمان
09 Body		جسم المركبة
09.A Fenders	FRONT & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
09.B Bumper	REPAINTED	دعامية
09.C Doors	FRONT & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	أبواب
09.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
09.E Trunk	PORTION REPAINTED,PORTION REPAIRED	صندوق
09.F Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS ,FLOOR GETTING MINOR RUSTY	صدأ
10 Interior Condition		الحالة الداخلية
10.A AC Condition	NOT WORKING	المكيف
10.B Sunroof	NOT WORKING	فتحت سقف
10.C Mirror	FOLDING NOT WORKING	المرايا
10.D Dash Board	DASHBOARD CONSOLE BOX LOOSE	لوحة القيادة
10.E Sun Visor	BOTH SIDE GLASS COVER MISSING	حاجب الشمس
11 Tires and Rims Condition		الاطارات
11.A Front Tyre	BOTH SIDE 2020 MINOR WORN OUT	الاطار الامامي
11.B Rear Tyre	BOTH SIDE 2019/2020	الاطار الخلفي
11.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.