

Queue Number 2800850

Transaction Date 25 Sep 2026, 16:55:53

Site Name
840 - Emirates AuctionsTransaction Number
26882012 (CC10009) (CC10012)

Vehicle Details

Chassis Number 1C4RDJDGXF*****
 Specification GCC Specification
 Make Dodge
 Model Durango
 Model Year 2015
 Color Black
 Mileage 165953 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Bumper	MISALIGN	دعامية
01.D Bonnet	SHOCK WEAK NOT WORKING	غطاء المحرك
01.E Trunk	PORTION REPAINTED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY, ABNORMAL NOISY SHAKING	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY, JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPENSION REFITTED	اخرى
09 Interior Condition		الحالة الداخلية
09.A AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae