

Queue Number

2852168

Transaction Date

09 Oct 2026, 16:36:13

Site Name

840 - Emirates Auctions

Transaction Number

59112445 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JTDKW92318*****
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2008
Color	Black
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE & FRONT RIGHT SIDE REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Floor	UNDER FLOOR , RUNNING BOARD DENT , MUDDY	الارضية
01.D Bumper	MISALIGN , MINOR SCRATCHES DENTS , GRILL PORTION LOOSE	دعامية
01.E Roof	REPAINTED PORTION FADED	السقف
01.F Bonnet	REFITTED	غطاء المحرك
01.G Trunk	NOT OPENING	صندوق
01.H Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE CHASSIS END REPAIRED , DENT	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	OIL PAN DENT , ENGINE ROOM WIRING FIX PROPERLY UNSAFE	اخرى
03.B Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY , OIL WET	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK , EXTRA COVER	حالة المقاعد
---------------------	-----------------------------	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST PIPE CUT REWELDED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY , OIL WET	الحالة النظرية للجير
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED , ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08.B Indicator & Hazard light	LEFT SIDE FADED , RIGHT SIDE LOOSE	الاشارات
08.C Fog light	MODIFIED	كشف الضباب
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك و طنايبير الفرامل
10 Suspension System		ممتص الصدمات
10.A Suspension Subframe	REAR BUSHES CRACK	ازرع
10.B Arms	BUSHES CRACK	
11 Interior Condition		الحالة الداخلية
11.A Other	CENTER CONSOLE PANEL PORTION WORN OUT , INETERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
11.B AC Condition	NOT CHECK , CONTROL PANEL PORTION WORN OUT	المكيف
11.C Floor Matting	DIRTY	فرش الأرضية
11.D Audio	CONTROL PANEL PORTION WORN OUT	صوتيات
11.E Dash Board	PORTION WORN OUT , GLOBE BOX DAMAGE	لوحة القيادة
11.F Roof Ceiling	FABRIC PORTION LOOSE	بطانه السقف
11.G Sun Visor	BOTH SIDE LOOSE	حاجب الشمس
11.H Door Panel	WORN OUT	لوحة بطانة الباب
11.I Steering Wheel and control buttons	PORTION WORN OUT , LOGO GETTING FADED	عجلة القيادة وازرار التحكم
11.J Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae