CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2906061 |
| Transaction Date | 28 Oct 2026, 16:36:45 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 44697060 (CC10006) (CC10011) |




**Vehicle Details**

| | |
|---|---|
| Chassis Number | 1N4AL21D08******* |
| Specification | GCC Specification |
| Make | Nissan |
| Model | Altima |
| Model Year | 2008 |
| Color | Silver |
| Mileage | 471674 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Fenders | FRONT RIGHT SIDE REFITTED | مدكار |
| 01.B Paint | BODY REPAINTED PORTION REPAIRED,FADED PORTION RUSTY | الصبغ |
| 01.C Floor | UNDER FLOOR RUST PROOFED, PORTION DENT, BACK PANEL REPAIRED, MUDDY, PORTION RUSTY | الارضية |
| 01.D Bumper | MISALIGN PORTION DAMAGED | دعامية |
| 01.E Windshield | PORTION CRACK | زجاج |
| 01.F Bonnet | STAY ROD MISSING | غطاء المحرك |
| 01.G Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 01.H Sign of back accident | | وجود مؤشر لحادث في الخلف |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | COVERD, OILY, MUDDY CHECKED VISIBLE AREA ONLY FRONT CHASSIS END & REAR EXTENSION END REPAIRED | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Mount | BUSHES CUT | كرسي |
| 03.B Engine Visual Condition | ENGINE NOT START, ALL SYSTEM NOT CHECK, REFITTED, OIL LEAK, PARTS RUSTY | الحالة النظريه للمحرك |
| **04 Seats Condition** | | المقاعد |
| 04.A Seat Condition | PORTION DAMAGED | حالة المقاعد |

| Condition | Remarks | الحالة |
|---|---|---|
| **05 Transmission Condition** | | الجير |
| 05.A Gear Box Visual Condition | NOT CHECK,REFITTED, OIL LEAK, PARTS RUSTY | الحالة النظريه للجير |
| 05.B Gear Box Mount | BUSHES CRACKED | كرسي الجير |
| 05.C Road Test | NOT CHECK | فحص علي الطريق |
| **06 Tires and Rims Condition** | | الاطارات |
| 06.A Front Tyre | BOTH SIDE 2022 CRACKED | الاطار الامامي |
| 06.B Rear Tyre | BOTH SIDE 2022 CRACKED | الاطار الخلفي |
| **07 Lights** | | الاضاءة |
| 07.A Head Light | LENS FADED ALL LIGHT NOT CHECK | الاضاءة الرئيسية |
| 07.B Tail Light | PORTION CRACKED | الضوء الخلفي |
| **08 Suspension System** | | ممتص الصدمات |
| 08.A Arms | BUSHES CUT | ازرع |
| **09 Interior Condition** | | الحاله الداخليه |
| 09.A Other | CENTER CONSOLE BOX DAMAGED, INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED | اخري |
| 09.B Mirror | CENTER MISSING | المرايا |
| 09.C AC Condition | NOT CHECK | المكيف |
| 09.D Dash Board | PORTION DAMAGED WORN OUT | لوحة القياده |
| 09.E Sun Visor | LOOSE | حاجب الشمس |
| 09.F Door Panel | PORTION DAMAGED | لوحة بطانة الباب |
| 09.G Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 09.H Gear Shifting Lever | KNOB WORN OUT | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**