



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **23 Oct 2021, 17:56:47**  
 Transaction Number **71207306 (CC10006)** Queue Number **312309**



Chassis Number **MROFR22G470635028**  
 Engine Number  
 Vehicle Class **Heavy**  
 Manufacturer **Toyota**  
 Model **Hilux**  
 Model Year **2007**  
 Color **White**  
 Mileage **852696 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED	الصبغ
01.B Floor	REAR CARRIER BOX,FLOOR ,WHEEL HOUSING REPAIRED	الارضية
01.C Rusty	UNDER BODY PART ,CHASSIS ,FLOOR GETTING RUSTY	صدأ
<b>02 Seats Condition</b>		<b>المقاعد</b>
02.A Seat Belt	FRONT LEFT WORNOUT	حزام الأمان
02.B Seat Condition	SEAT HAVE EXTRA COVER &COVER CUT	حالة المقاعد
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
<b>04 Chassis Condition</b>		<b>الشاسي</b>
04.A Chassis	REAR RIGHT CHASSIS REPAIRED&CHASSIS FRAME RUSTY PORTION ,BULDGE BEND	الشاسيه
<b>05 Wipers and Arms</b>		<b>المساحات</b>
05.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
<b>06 Engine Condition</b>		<b>المحرك</b>

DEFECT	REMARKS	
06.A Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Gear Box	OK	الجير
08 Interior Condition		الحالة الداخليه
08.A AC Condition	OK	المكيف
09 Lights		الاضاءة
09.A Head Light	OK	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.