



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 May 2023, 11:21:09
Transaction Number	80729829 (CC10013)	Queue Number	727596



Chassis Number	KNMCC42HX8P685464
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Sunny
Model Year	2008
Color	Gold
Mileage	342228 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Chassis Condition		الشاسي
01.A Chassis Number	STICKER FADED	رقم القاعدة
01.B Chassis	FRONT LEFT SIDE CHASSIS END MINOR BEND	الشاسيه
02 Body		جسم المركبة
02.A Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY & MUDDY	صدأ
02.B Bumper	MISALIGN MINOR DENT	دعامية
02.C Windshield	FRONT SPOT CRACK	زجاج
02.D Paint	BODY PORTION REPAINTED PORTION REPAIRED PORTION RUSTY & FADED MINOR DENT SCRATCHES	الصبغ
02.E Other	BUMPER FRAME RADIATOR SUPPORT BULK HEAD REPAIRED (LOGO MISSING)	اخرى
02.F Floor	UNDER FLOOR FULLY MUDDY MINOR DENT NOT VISIBLE,	الارضية
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	SIGN OF MINOR OIL LEAK JERKING	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق
04 Exhaust System		نظام العادم

DEFECT	REMARKS	
04.A Other	LEAK MISALIGN	اخرى
05 Interior Condition		الحالة الداخلية
05.A AC Condition	NOT WORKING SWITCH PANEL BUTTON DAMAGED	المكيف
05.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
05.C Power Window Switch	FRONT RIGHT SIDE & REAR LEFT SIDE NOT WORKING	مفتاح النافذه
05.D Audio	REAR SPEAKER COVER WORN OUT	صوتيات
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2019 DAMAGED CRACKED	الاطار الامامي
06.B Rear Tyre	2019 DAMAGED CRACKED	الاطار الخلفي
06.C Rims Condition	BEND	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSH CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Shock Absorber	ALL WEAK	ممتص الصدمات
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Engine Condition		المحرك
09.A Visual Engine Condition	SIGN OF MINOR OIL LEAK FULLY MUDDY MISFIRING	حالة المحرك النظري
09.B Mount	MOUNT RUBBER CRACK	كرسي
09.C Smoke	BLACK	دخان
10 Steering Condition		المقود
10.A Other	STABILIZER LINK BOOT CUT	اخرى
10.B Steering Oil	OIL WET	زيت المقود
10.C Steering Boot	BOOT CUT	ربلة المقود
10.D Tie Rod End	BOOT CUT	مؤخرة الرودادت
10.E Axle	SIGN OF CRACK	اكسلات
11 Lights		الاضاءة
11.A Fog light	NOT WORKING	كشاف الضباب
11.B Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Car Check does not guarantee the vehicle's fitness for registration.